



Case Study: New Technologies Improve Motorization

Introducing the Anti-Blocking System



Problem:

- Motorized shutter doors can become damaged if downward progress becomes blocked
- Damages resulting from improper operation are expensive to fix and are not covered by Rollok warranty
- Other systems providing a similar function are expensive; requiring additional parts and installation

Solution:

- The Anti-Blocking System now available at Rollok is an inexpensive safeguard
- If the door meets an obstacle when lowering, the motor idles, preventing motor burnout and compromised security
- Motorized doors provide simple security without risk of damage

